

April 1958

INDEX

ISSUE No. 11
(Please destroy
previous issue)

to

IMPROVEMENTS AND ALTERATIONS

This Index embodies all information issued up to and including Service Memorandum No. MG/213 and Parts List Amendment No. PMG/270. Workshop Manual references, where applicable, are shown in italics and may include any additional or amended sheet issued to date.

Figures in heavy type denote that the change is embodied in the current Parts List (Part No. AKD688).

SUBJECT	Information issued under		SUBJECT	Information issued under	
	Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/		Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/
GENERAL			Camshaft		
Grease gun			—gear and locating plate— modified to suit new timing chain tensioner	167 (A22)	47
—hydraulic nozzle fitted ..		37	—gear—modified to maintain correct tooth position when joint washer is not fitted ..		48
Misfiring and oiling up of spark- ing plugs—investigation and rectification	150		—joint washer—locating plate deleted to reduce distortion of thrust plate		48
Paintwork			Carburetter		
—Birch Grey body colour ..	168	49, 234	—coupling—modified to im- prove 'take-off'	210, 211	257, 258
—Duotone finish introduced ..		124 to 128, 234, 236	—distance piece—made of harder material to prevent breaking up and fracturing of carbur- etter flange	213	268
—Green and Grey—straight cellulose replaces metallic finish	148	47, 234	—modified		27
—Island Green body colour ..	167	50	Clutch		
—Red body colour	169	52	—housing—ingress of dust and water—prevention	201	
—Royal Tan body colour ..	169	86	—(Manumatic) — filler cap — deeper type introduced to give more thread engagement		267
—Royal Tan body colour dis- continued	173	45, 234	—withdrawal lever — locknut replaces nut and spring wash- er to prevent nut becoming loose		81
—Steel Blue body colour ..	166	234	—withdrawal lever bolt—larger diameter. Bush to suit to prevent overtightening ..	(E7)	104
—touch-up paints		37	Connecting rods		
—touch-up pencils introduced			—increased section around bearing portion		108
—Twilight Grey body colour re-introduced	173	86, 234	Crankshaft		
Tool kit			—alternative		30
—jack—circular spigot intro- duced to improve jacking ..	195	131			
—jack—to suit side jacking ..	178	99			
'ZB' Model					
—introduction		120 to 128, 131, 233, 234			
POWER UNIT					
Air cleaner					
—oil bath type introduced ..	178	97			

SUBJECT	Information issued under		SUBJECT	Information issued under	
	Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/		Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/
Power Unit—continued			Cylinder head		
Crankshaft—continued			—exhaust manifold—modified		259
—bearings—main—single lubrication hole		97, 100	—exhaust throat diameter reduced to improve power output	148	26
—pulley—flange—timing notch to facilitate timing	148 (C9)	26	—gasket—copper and asbestos replaces copper, steel, and asbestos to improve sealing	206	249
—pulley—to suit wedge-type fan belt	147	24	—gasket—copper ferrules fitted to improve sealing	206	
—shape and width of webs modified		48	—gasket—copper, steel and asbestos replaces steel type	148 (A22)	26
Cylinder block			—gasket—reinforcing strip modified	154	
—blanking plate—set screws replaced by studs and nuts ..		85	—gasket—Service replacements for engines prior to 3977 ..		88
—crankcase—timing indicator welded to front cover to facilitate timing	148 (C9)	26	—heater outlet—diameter increased to reduce restriction in flow from head to heater outlet pipe	198	
—front cover—modified to suit new timing chain tensioner	167	47	—inlet ports—modified to improve power output ..	148	26
—modified to suit new timing chain tensioner	167	47	—studs and nuts—modified to improve cylinder head joint..	166	40
—oil dipper rod—chamfers added to lower end to facilitate insertion of rod into crankcase	154		—valve guide bore increased (inlet)—standardization with exhaust valve		265
—oil dipper rod—improved accessibility	209		—valve rocker and tappet adjusting screw—length increased to prevent screw working loose	147	19
—oil dipper rod—minimum level mark added	154	249	—valve rocker shaft brackets—improved design		96
—oil dipper rod—shortened ..			Distributor		
—oil feed drilling—to suit modified oil pump driving spindle	147 (A21)	19	—fitted with improved contact breaker	(C10)	84
—oil gallery—chamfer added to prevent oil leaks	151		—fuel—entering head—prevention	182	103
—oil pipe union— $\frac{1}{4}$ in. British Standard Pipe thread to prevent oil leaks	145	19	—modified advance curve and suction setting to improve design		254
—plug above oil release valve—taper plug replaced by screwed type to prevent oil leaks ..	145	19, 22	—modified to improve run of ignition cables		84
—plug—taper—oil filter boss—diameter increased to prevent oil leaks	145	19	Dynamo		
—rear main bearing oil leaks —Service rectification ..	212		—modified body construction	(N19)	84
—water drain tap—design improvement		50, 259	—pulley—diameter reduced to increase dynamo speed ..	205	245

SUBJECT	Information issued under		SUBJECT	Information issued under	
	Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/		Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/
Power Unit—continued			Gearbox—continued		
Dynamo—continued			—change speed lever tower—set screws replace studs and nuts		96
—pulley—modified to suit wedge-type fan belt	147	24	—dipstick—length increased ..	143	
Engine mounting			—dipstick—low mark raised to ensure adequate lubrication of speedometer drive ..	147	
—plate—front—modified to suit new timing chain tensioner	167	47	—extension—modified ..		31
—rubbers—front—harder to prevent gear lever vibration	199	232	—extension—oil seal—improved type		86
Fan			—extension—oil seal modified to improve sealing	210	254
—belt—shorter type to suit smaller-diameter dynamo pulley	205	245	—first motion shaft—oil baffle fitted to improve sealing at front cover		89
—belt—wedge type introduced	147	24	—first speed gear—crown profiled to improve engagement of first gear	164	
—blades—reshaped to improve design		123	—fork—first, second, third, fourth, and reverse—lugs deleted and locating block width increased to improve accessibility of locating screws ..	169	50, 81
Flywheel			—fork—third and fourth—improved design		269
—bolts—nuts of improved material to improve design	154	29	—fork locating screws—improved accessibility	169	50
Gearbox			—front cover—oil seal fitted to improve seal between front cover and first motion shaft	182 (F8)	104
—change speed fork locating screws—locknuts replace locking wire	143	22	—layshaft gears—crown profiled to improve engagement of first and reverse gears	164	
—change speed gate—deleted to improve accessibility of fork locating screws	169	50	—layshaft gear unit—interchangeability		50
—change speed gate—modified		24	—mounting plate—thicker gauge to improve design ..	182	104, 233
—change speed lever knob—rubber insert fitted to prevent vibration	202	241	—mounting plate—oil escape groove and recess in front face to improve design ..	182	104
—change speed lever—retaining spring modified to prevent lever pulling through spring	7 (F8)	37	—reverse fork shaft—angular detent groove to prevent auto-disengagement of reverse gear	143	20
—change speed lever tower—modified to suit rectangular section circlip to ensure positive fixing for spring cover and to facilitate gear change cross selection ..	151	28			
—change speed lever tower—reverse plunger spring plug replaced by set screw to improve location of spring ..	164	39			
—change speed lever tower—screwed locating pin to prevent pin becoming loose ..	164	39			

SUBJECT	Information issued under		SUBJECT	Information issued under	
	Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/		Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/
Power Unit—continued			Gearbox—continued		
Gearbox—continued			—speedometer pinion bush— joint washer—alternative ..		26
—reverse gear—crown profiled to improve engagement of reverse gear ..	164		—speedometer pinion bush— joint washer—copper—to prevent oil leaks ..	147	24
—reverse plunger spring—shortened		96	—speedometer pinion bush— modified to prevent oil leaks	163	
—reverse shaft—diameter increased to prevent auto-disengagement of reverse gear	148	26	Gearbox mounting		
—second speed gear and baulk ring—cone angle reduced to improve synchro. action ..	143	20	—fixing bolts and nuts— material changed to ensure tight fixing		90
—second speed synchronizer— outside diameter increased to prevent auto-disengagement of first and reverse gears ..	143		Ignition coil		
—second speed synchronizer— relieved teeth to prevent auto-disengagement of first speed gear	143	20	—bracket—modified to increase accessibility of dipper rod ..	209	
—second speed synchronizer— width of slots in front face reduced to facilitate engagement of third gear	205		—fluid-filled	(C2)	22
—selector lever—rear clamping screw to improve location on shaft	143		—mounted on dynamo ..		29
—selector lever—rear—longer reverse plunger pad		27	—steady plate introduced ..		95
—selector—third, fourth, and reverse—jaws with 45° chamfer to improve gear selection	161		Oil filter		
—selector—first, second, third, fourth, and reverse—bosses lengthened to provide overshoot stops	169	50	—Tecalemit—alternative ..		85, 266
—shaft—third, fourth, and reverse forks—conical holes repositioned to improve accessibility of fork locating screws	169	50	Oil pump		
—speedometer gear and pinion— 5/12 ratio to suit modified speedometer	147	23	—body—improved design to increase clearance between crankshaft and pump ..	147	20, 23
—speedometer pinion—nylon type introduced to ensure quieter running		245	—driving spindle—oil feed drilling	147 (A21)	20
			Pistons		
			—chrome-plated top ring to reduce oil consumption and prolong piston ring life ..	(A23)	119, 267
			—commonization	154	31, 114
			—fully split skirt	194	29
			—sizes for service		19, 24
			—'T' slotted		
			Power unit		
			—modified unit with full-flow oil filter, etc.	188	120, 243
			Push-rods		
			—end diameter increased to improve design	180 (A23)	102
			Starter		
			—pinion cover—to prevent ingress of dust and water into clutch housing	201	
			Sump		
			—protection plate—to prevent damage (Service)	200	

SUBJECT	Information issued under		SUBJECT	Information issued under	
	Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/		Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/
Power Unit—continued			TRANSMISSION AND REAR AXLE		
Tappets			Propeller shaft		
—ball seat—modified to suit new push-rods	180 (A23)	102	—modified and standardized type introduced		123, 238
Thermostat			Rear axle		
—jiggle pin added		35	—carrier—differential—modified		42, 257
—modified to give higher opening temperature		262, 266	—case—left-hand end threaded L.H. hub bearing locknuts and washers—modified to improve design	172 (H10)	84
Timing chain tensioner	167 (A22)	47, 50	—hub—oil seal—additional—to prevent leakage through flange joint	(H11)	122
—rubber slipper plate introduced to reduce noise ..		94	—shaft—increased diameter to facilitate machining	145	18
—service kit					
Vacuum ignition control pipe			SUSPENSION, STEERING, ROAD SPRINGS AND WHEELS, SHOCK ABSORBERS, AND BRAKES		
—fuel trap—incorporated to prevent fuel entering distributor	182 (C11)	103	Brakes		
—reshaped to prevent fouling carburettor heat shield ..	166	46	—cables—hand brake—covered with P.V.C. material to prevent ingress of water ..	202	241
Valves			—cables—hand brake—grease nipples fitted	169	36, 41, 50
—exhaust—lengthened to improve power output	148 (A22)	26	—cables—hand brake—revised attachment to hand brake lever to prevent cable end pulling through fork end ..		269
—inlet—modified		28	—cables—hand brake—washer introduced to prevent possibility of cable being pulled through fork end	208	257
—inlet—modified to suit larger diameter inlet guide bore ..		265	—drums—adjusting holes—seals (Service)	153	30
—oil seal—improvement in material	172, 180		—drums—adjusting holes—seals—standardized		18, 23
Valve guides			—hose bracket—front repositioned to prevent front brake hose fouling wheels ..	145	18, 19
—exhaust—shortened		101	—linings—Ferodo DM.12 replace MR.19 to improve braking	167 (M14)	47, 81
—inlet—bore increased—standardization with exhaust valve		265			
Valve rocker cover					
—inlet—shortened to suit modified cylinder head	148 (A22)	26			
—joint thickness increased to improve oil sealing	206	255			
Water outlet elbow					
—material improved to prevent corrosion by anti-freeze ..	177				
Water pump					
—oil filler plug—longer to improve accessibility	175	91			
—pulley and hub—modified ..		46, 63			
—pulley—to suit wedge-type fan belt	147	24			
—seal—alternative		42			
—vane—one-piece cast-iron to improve sealing	161	32			

SUBJECT	Information issued under		SUBJECT	Information issued under	
	Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/		Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/
Suspension, Steering, Road Springs, and Wheels, Shock Absorbers, and Brakes —continued			Accelerator pedal—continued		
Brakes—continued			—larger-diameter bolt—to prevent slip		38
—pipes—modified to suit repositioned front hose bracket	145	18, 19, 23	—spindle and lever—shaft shortened to avoid breakage ..		270
Front suspension			—spindle lever—hexagon head screw replaces round head to avoid breakages		47
—coil spring—to improve suspension	145 (5)	18	Body		
—pivot pin replacement ..	162 (K16)		—additional dust seals—method of fitting	187	
Road wheels			—'A' posts—filter pads fitted to improve dust sealing ..		95
—rubber plug—to improve sealing of brake-drums ..		18	—'B' and 'C' posts—sealing strips to improve dust sealing	151	
—tubeless tyres	163	38	—centre pillars—filter pads to improve dust sealing ..		22
Shock absorbers			—dash panel—rubberized felt pads fitted to improve sound-deadening	172	85
—front—covers modified to suit new brake pipe arrangement	145	18	—dash side—sealing strips to improve dust sealing ..	151	
—front—eyebolt with welded bottom anchorage pin replaces bolted assembly to prevent anchorage becoming loose	169 (K9)	53	—rear wheel arches—sealing	146 (R14)	
—rear—pivot arm—improved mounting	174		—sill cover plates introduced to cover paint drainage holes ..		46
Steering			Bonnet		
—outer ball socket—pin and grease in UNF threads ..		18, 65	—link assembly—redesigned to improve bonnet lift	154	29
—rack—'flat' provided to prevent rattle		236, 238, 250	—lock operating mechanism—rod replaces Bowden cable to facilitate control	148	26
— rack — housing — rubber bushes fitted at mounting points to eliminate noise ..	186 (J7)	109	—striker pin—tapered shank to increase efficiency of bonnet catch		90
—socket assemblies — UNF threads replace BSF type ..		264	—striker pin—UNF threads ..		35
—tie-rod—increased in diameter at ball-end to improve design	172	63, 84	—support rod—replacing torsion bar assisted lift to improve design	178	97
BODY, RADIATOR, PETROL AND EXHAUST SYSTEMS			Bumpers		
Accelerator pedal			—modified to coincide with side jacking		99
—adjustable pad now fitted ..		249	—rear—over-riders repositioned to improve visibility of number-plate		84
			Carpets		
			—front tunnel—fastener added to improve fixing		268

SUBJECT	Information issued under		SUBJECT	Information issued under	
	Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/		Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/
Body, Radiator, Petrol and Exhaust Systems—continued			Fuel system		
Carpets—continued			—pipes—flexible braided replaced by rubber type ..		258
—underfelt—increased in thickness to improve sound-deadening	172	85	Heater and demister		
Demister			—control cables — shortened to improve operation (LHD only)		108
—tubes, control quadrant, and knobs to suit new fascia ..	161	23, 33, 34	—flap control levers—repositioned to give improved cable run	(S3)	52
Doors			—heat deflector—introduced to improve design	169	53
—drain holes—filter pads to improve dust sealing ..		22	—ineffective temperature control and demister—rectification	179	
—front — flash moulding — improved fixing	161	34	Instrument panel and instruments		
—lock—strikers—gasket fitted to prevent strikers slipping	175	91	—clock—illuminated type introduced	176	92
—locks—children's safety locking device introduced ..	199	236	—control knobs—modified to obtain uniform projection of knobs from fascia		66
—sealing pads—added to prevent water entering interior	145		—flasher warning light—repositioned to improve visibility	171	65
—sealing pads—fitted to door hinge and check arm recesses to improve sealing	195	131	Jacking		
—sealing rubbers—sponge rubber to improve appearance and efficiency	145	16	—conversion from fore-and-aft to side jacking	181	
—sealing strips—fitted to inner panels to improve dust sealing	180, 191		—jack—circular spigot introduced to improve jacking ..	195	131, 241
—ventilators—hinge line altered to more vertical angle		98, 112	—side jacking introduced ..	178	99
Exhaust system			Mirror		
—method of fixing to gearbox extension modified		232	—steady arm — incorporated to improve stability and rear vision	163	37
—rear pipe—diameter increased to improve performance ..	213	269	Number-plate		
—revised layout		236	—rear—lowered to improve visibility		84
—silencer—standardized type introduced to improve performance	213	269	Paintwork		
Fascia			—Birch Grey body colour ..	168	49, 234
—improved design	161 (R10)	32, 33, 34, 39, 66	—Duotone finish introduced ..		124 to 128, 234, 236
—oil gauge—pipe lengthened (LHD)		232	—Green and Grey—straight cellulose replaces metallic finish	148	
—warning light glass—changed from green to amber to improve 'noticeability' ..		252	—Island Green body colour ..	167	47, 234
			—Red body colour	169	50
			—Royal Tan body colour ..	169	52

SUBJECT	Information issued under		SUBJECT	Information issued under	
	Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/		Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/
Body, Radiator, Petrol and Exhaust Systems—continued			Seats		
Paintwork—continued			—front frames—lowered to improve seating position ..	173	87
—Royal Tan body colour discontinued	173	86	—front—passenger's—prevention of rattle	156	
—Steel Blue body colour ..	166	45, 234	—front—slides and frame modified		41, 86
—touch-up paint		234	—front—wooden block added to leading edge of frames to improve comfort	186	109
—touch-up pencils introduced		37	—rear squab—additional millboard liners fitted to improve sealing against petrol fumes	191	
—Twilight Grey body colour re-introduced	173	86, 234	Speedometer		
Parcel tray			—1,600 revs. per mile type ..	147	24
—additional millboard liners			—cable—PVC covering introduced		232
—fitted to improve sealing against petrol fumes ..	191		Sun visor		
Petrol filler			—location	165	
—hose—extension—material changed to improve life ..		23	—longer screws—visor to header panel		43
—lock—Yale type incorporating dust shutter to improve locking and dust-sealing ..	145	19	—packing block—reshaped to improve angle of visor mounting	171	65
—lock—Yale type replaced by plunger - type operating mechanism—improved design	170	62	Tonneau side panel		
Petrol pipes			—additional paint drainage holes		46
—longer main pipe and shorter flexible pipe—to suit revised jacking system		241	Trunk lid		
Petrol pump			—lock—protective cover to prevent luggage fouling lock	164	39
—light compression spring—to prevent siphoning back ..	147	23	—lock—Yale type		28
Petrol tank			Ventilator (dash)		
—filler gauge attachment—anti-rattle ring added		27	—cable—shortened to improve operation (LHD only) ..		108
—filler gauge attachment—UNF screws		27	—cable—shortened to relieve strain on quadrant control ..		243
Radiator			—fitting additional drain tube to ventilator box to improve water drainage	149, 168 (R10)	49
—case assembly—modified to suit new grille slats		40	—lid—deflector plate introduced to improve water sealing	168 (R11)	48, 90
—grille outer slats—part of side case panels		40	Windscreen		
—nose-piece and dummy filler—standardized with 'TF' model		40	—inside cappings—to suit new fascia	161	32 to 34
Roof panel			—top fillet—modified to suit new sun visor mounting ..	171	
—additional paint drainage holes		46			
Scuttle trim pads					
—standardized for both RHD and LHD cars		46			

SUBJECT	Information issued under		SUBJECT	Information issued under	
	Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/		Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/
Body, Radiator, Petrol, and Exhaust Systems—continued			Ignition coil		
Windscreen washer			—bracket modified to increase accessibility of dipper rod ..	209	
—bottle bracket—modified to increase accessibility of dipper rod	209	259	—fluid-filled	(C2)	22
—improved design	171	65	—mounted on dynamo ..		29
—'T' piece—liquid hose—material change		63	—steady plate introduced ..		95
Wings			Sidelamps (flasher)		
—front—flash moulding—improved fixing	161		—clear glass replacing shot-blasted lens		30
—front—P.V.C. piping replaced by Prestik sealer		43	Starter		
			—pinion cover—to prevent ingress of dust and water into clutch housing	201	
			Stop/tail lamp		
			—rims—chromium-plated ..		20, 23
			—reflectors incorporated ..		23
			Windscreen wiper		
			—blade—modified to prevent scratching of screen and to give improved wipe		237
ELECTRICAL EQUIPMENT					
Clock			LITERATURE		
—illuminated type introduced	176	92	List of Suggested Stock Holdings.		
Distributor			Maintenance Service Vouchers—		
—fitted with improved contact breaker	(C10)	84	Part No. AKD727.		
—fuel entering head—prevention	182	103	Mono-construction Book—Part		
—modified advance curve and suction setting		254	No. AKD574.		
—modified to improve run of ignition cables		84	Operation Manuals—up to Car No.		
Dynamo			18100—Part No. AKD572E.		
—modified body construction	(N19)	84	—from Car No. 18101 (ZB)—		
—pulley—diameter reduced to increase dynamo speed ..	205	245	Part No. AKD687F.		
—pulley—modified to suit wedge-type fan belt	147	24	—including Manumatic Control		
Horns			—Part No. AKD687J.		
—improved		27	Parts List (May 1957)—Part No.		
—packing piece—deleted and brackets modified to increase clearance		30	AKD688.		
—packing piece—horn bracket		27	Parts List Amendments Nos.		
—water exclusion	133		PMG/236 to 238, 241 to 243,		
—water shields—fitted to prevent water entering horns ..	175	91	245, 247 to 270.		
			Price List (April 1957)—Part No.		
			AKD693.		
			Supplements Nos. I to II.		
			Schedule of Repair and Adjustment Time Allowances—Part		
			No. AKD783A.		

SUBJECT	Information issued under		SUBJECT	Information issued under	
	Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/		Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/
<p>Literature—continued</p> <p>Schedule of Repair Charges—Part No. AKD840.</p> <p>Service Parts List—Part No. AKD-688.</p> <p>Service Tool Catalogue—Part No. AKD659.</p> <p>The following have been issued for the above Catalogue:</p> <p>Amended Sheets—Issue No. 2—iii and iv.</p> <p>Workshop Manual—Part No. AKD573.</p> <p>The following have been issued for the above Manual:</p> <p>Additional Sheets—A.23; C.11; K.9; N.21; O.7; Q.17; SA.1 to SA.6, SA.9 to SA.37.</p> <p>Amended Sheets—Issue No. 2—15 and 16; A.3, A.4, A.13 to A.16; B.3, B.4; D.1, D.2; E.1, E.2; F.3, F.4; H.3, H.4; I.1, I.2; K.3 to K.8; M.1, M.2, M.5, M.6; N.9, N.10, N.17 to N.20; O.5 to O.8; Q.9 to Q.16; R.11; S.3; Lubrication Chart (commencing Car No. ZB18577).</p> <p>Amended Sheets—Issue No. 3—1 to 4; A.17, A.18; B.13, B.14; C.5, C.6; D.3, D.4; F.7, F.8; H.11; J.1, J.2, J.7; K.1, K.2; L.1, L.2; M.11 to M.14; N.13, N.14; O.1, O.2; Q.5 to Q.8; R.7, R.8; SA.7, SA.8.</p> <p>Amended Sheets—Issue No. 4—7 and 8, 13 and 14; A.5, A.6; B.1, B.2, B.5, B.6; C.1, C.2, C.9, C.10; E.7; F.1, F.2; H.7, H.8; N.1, N.2; P.5; Q.3, Q.4.</p> <p>Amended Sheets—Issue No. 5—9 and 10; A.1, A.2, A.19, A.20; H.1, H.2, H.9, H.10; N.15, N.16; P.3, P.4; Q.1, Q.2; R.9, R.10; S.1, S.2; Lubrication Chart (up to Car No. ZA18576).</p> <p>Amended Sheets—Issue No. 6—11 and 12; A.21, A.22.</p>			<p>Literature—continued</p> <p>Amended Sheets—Issue No. 7—R.1, R.2.</p> <p>Amended Sheets—Issue No. 8—5 and 6; P.1, P.2; Key to Recommended Lubricants.</p> <p>Amended Sheets—Issue No. 9—5 and 6.</p>		

