

# SERVICE MEMORANDUM

6 February 1959

IMPORTANT MODIFICATIONS

Parts List  
Amendment No.

Spigot -  
front spring

From Car No. 58996 - MGA )  
842 - MGA Twin-Cam )

PMG/314

Improved design

Outside diameter of spigot increased  
to 2.74"/2.75" (6.86/6.98 mm.)  
from 2.67"/2.66" (6.48/6.76 mm.)

Interchangeable.

Pistons -  
scraper rings

From Engine No. 446 - MGA Twin-Cam

PMG/331

Improved design

Twin-segment scraper rings fitted.

Interchangeable.

Oil pump drive  
spindle -  
half-speed shaft

From Engine No. 315 )  
plus 313 ) MGA Twin-Cam

PMG/331

To reduce wear on gear teeth

Number of teeth of oil pump drive  
spindle increased from 10 to 11;  
tooth-angle of half-speed shaft  
modified to suit.

Interchangeable together.