

# CONFIDENTIAL

MG/258

## SERVICE MEMORANDUM

MGF/22

18 June 1959

### CARBURETTOR PISTON ICING

MAGNETTE III  
M G A

This trouble may occur and lead to starting difficulties, even with an induction heater fitted.

The accompanying sketch shows the installation of a suction chamber heater element, Part No. AUC1279, which will satisfactorily overcome piston freezing at sub-zero temperatures.

Note that the element is turned so as to give ample clearance between the terminal 'A' and the air pipe before tightening up the tongued clip 'B'.

In making the connection with clip ACA5119, ensure good contact by removing paint from thermostat shell.

