

**CONFIDENTIAL**

MG/267

# **SERVICE MEMORANDUM**

MGF/25

29 July 1959

## FLYWHEEL DOWELS

To facilitate removal, a 5/32" hole may be drilled from the back of the flywheel into each dowel hole.

This will allow the dowels to be knocked out with a  $\frac{1}{8}$ " punch.