

CONFIDENTIAL

MG / 324

SERVICE MEMORANDUM

MGF/51

27 July 1960

CONTROL BOX (Part Nos. 3H1835 & 3H1836)

An improved wire-wound resistance, Part No. 47H5589, has recently been incorporated in the above, replacing the earlier carbon-composition type, Part No. 7H5066.

Although the part numbers of the control boxes remain unchanged, the resistances are NOT interchangeable.

It is essential, therefore, to note that, in Service, the original resistance, Part No. 7H5066, is fitted to control boxes bearing the manufacturer's numbers

37182A to 37182J (for control box 3H1835) and
37183A to 37183K (for control box 3H1836).

The later resistance, Part No. 47H5589, is fitted to control boxes bearing the manufacturer's numbers 37182K (for 3H1835) and 37183L or 37183M (for 3H1836).