

CONFIDENTIAL

MG / 330

SERVICE MEMORANDUM

MGF / 54

5 October 1960

UNDERSEALING

ALL MODELS

Isolated cases of careless application of underseal have caused the blocking of rear axle oil breathers, chassis lubrication points, etc.,

It is essential that Workshop personnel be reminded that proper and adequate masking is essential before undersealing is undertaken.