

**CONFIDENTIAL**

MG / 347

**SERVICE MEMORANDUM**

MGF/61

8 Feb 1961

STARTER BRUSH SPRINGS

All vehicles fitted  
with M35G/1 starters

The commutator end bracket, Part No. 7H5041, fitted to M35G/1 starters has recently been modified without change of Part No.

Earlier brackets incorporated brass brush boxes, each with a split support post. Current production have steel brush boxes with single spring support posts.

It is essential, therefore, that the correct brush springs are ordered for replacement purposes:  
for the earlier brackets use brush spring set, Part No. 7H7043, and  
for the current type, use brush spring set, Part No. 47H5341.